


3. UPGRADE KIT FOR CHANGING TO NEW BEARING AND ADJUSTMENT BRACKET IN THE SHUTTLE FOR HM604 LOOMS



OBS
SHUTTLE HAND
SCREWS MUST BE
CUT TO FIT THE
NEW ADJUSTMENT
BRACKET FOR
SHUTTLE HANDS

PARTS REQUIRED AND COST (2020)

| Our Item No. | Our description | Quantity | Unit | Unit Price | Amount |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------|----------|------|------------|--------|
| 5280.000 | Kit: New bearing, adj. bracket for 2 shuttle. Ex. Shuttle hand and adj. screw (637) OBS! Sh. hand and screw must be cut. See instructions | 2 | PCS | | |

Total NOK _____

DATE: 00/00/000